

REGULATOR INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR:8007220394 DOC.DATE: 80/07/15 NOTARIZED: NO DOCKET #
 FACIL:50-331 Duane Arnold Energy Center, Iowa Electric Light & Pow 05000331
 AUTH.NAME AUTHOR AFFILIATION
 MINECK,D.L. Iowa Electric Light & Power Co.
 RECIP.NAME RECIPIENT AFFILIATION
 DENTON,H.R. Office of Nuclear Reactor Regulation, Director

SUBJECT: Forwards "Reacotr Containment Local Leakage Rate Testing,
 1980 Outage."

DISTRIBUTION CODE: A017S COPIES RECEIVED:LTR 1 ENCL 1 SIZE: 1+21
 TITLE: Containment Leak Rate Testing - Appendix J

NOTES:

ACTION:	RECIPIENT ID CODE/NAME	COPIES		RECIPIENT ID CODE/NAME	COPIES	
		LTTR	ENCL		LTTR	ENCL
ACTION:	IPPOLITO,T. 05	1	1	KEVERN,T.	1	1
INTERNAL:	A/D CORE & CS	1	0	CONT SYS BR 22	1	1
	D/DIR,HUM FAC S	1	0	I&E 12	2	2
	NRC PDR 02	1	1	OELD 21	1	1
	OR ASSESS BR 18	1	1	PROC/TST REV BR	1	1
	REG FILE 01	1	1			
EXTERNAL:	ACRS 24	16	16	LPDR 03	1	1
	NSIC 04	1	1			

JUL 23 1980

TOTAL NUMBER OF COPIES REQUIRED: LTTR 30 ENCL 28

MA
4

60

Iowa Electric Light and Power Company

July 15, 1980
DAEC - 80 - 330

Mr. Harold Denton, Director
Office of Nuclear Reactor Regulation
U.S. Nuclear Regulatory Commission
1717 H Street N.W.
Washington, D. C. 20545

Re: Duane Arnold Energy Center

Subject: 1980 Reactor Containment Local Leak Rate Tests

File: A-110

Dear Mr. Denton:

In accordance with Section 4.7.A.2.f of DAEC Technical Specifications and Regulatory Guide 10.1, please find enclosed the Reactor Containment Local Leak Rate Test Report for B and C tests conducted at DAEC during the 1980 refueling outage.

Very truly yours,



Daniel L. Mineck
Chief Engineer
Duane Arnold Energy Center

DLM/JVS/rs

Enclosure

A017
S.11